

SITE INSPECTION FORM

Date: 6/7/2022
Address: 80 State Highway Route 6

Building Name/Number: CABIN #4

Building Features

| | | | | | | | | | |
|----------------------------|--|------|------------|-----------|----------------------|------|------|-------------------|--|
| Building Construction Type | | | Wood Frame | Cmu Block | Wood Frame/Cmu Block | | | Metal Mobile Home | |
| Location: | | | | | | | | | |
| Roof | | Type | ASPHALT | Front | Condition: New | Good | Fair | Poor | |
| | | | | Rear | Condition: New | Good | Fair | Poor | |

Comments: _____

| | | | | | | | | | |
|----------------|--|------|------|-----------|-------|----------------|------|------|------|
| Exterior Walls | | Type | WOOD | Location: | North | Condition: New | Good | CAA | Poor |
| | | | | | South | Condition: New | Good | Fair | Poor |
| | | | | | East | Condition: New | Good | Fair | Poor |
| | | | | | West | Condition: New | Good | Fair | Poor |

Comments: All exterior walls above grade

| | | | | | | | | | |
|---------------|--|------|---------|-----------|-------|----------------|------|------|------|
| Windows/Doors | | Type | UNKNOWN | Location: | North | Condition: New | Good | Fair | Poor |
| | | | | | South | Condition: New | Good | Fair | Poor |
| | | | | | East | Condition: New | Good | Fair | Poor |
| | | | | | West | Condition: New | Good | Fair | Poor |

Comments: _____

| Foundation | | Type | Slab | Crawlspace | Yes | No | | | |
|------------|--|------|---------------------|------------|------------|-----|------|------|------|
| | | | Frost Wall | | | | | | |
| | | | On Cmu Blocks/Piers | North | Condition: | New | Good | Fair | Poor |
| | | | Full Foundation | South | Condition: | New | Good | Fair | Poor |
| | | | | East | Condition: | New | Good | Fair | Poor |
| | | | | West | Condition: | New | Good | Fair | Poor |

Comments: _____

| | | | | | | | | |
|-----------|--|--------------|--------------|-------|----------------|------|------|------|
| Interior: | | Ceiling Type | CEILING TILE | North | Condition: New | Good | Fair | Poor |
| | | | | South | Condition: New | Good | Fair | Poor |
| | | | | East | Condition: New | Good | Fair | Poor |
| | | | | West | Condition: New | Good | Fair | Poor |

Comments: Homasote Ceiling Tiles

| | | | | | | |
|-----------|---------------|-------|----------------|------|------|------|
| Wall Type | WALL BOARD | North | Condition: New | Good | Fair | Poor |
| | WOOD WAINSCOT | South | Condition: New | Good | Fair | Poor |
| | | East | Condition: New | Good | Fair | Poor |
| | | West | Condition: New | Good | Fair | Poor |

Comments: Homasote Wall Board

| | | | | | | |
|------------|--------|-------|----------------|------|------|------|
| Floor Type | Vinyl | North | Condition: New | Good | Fair | Poor |
| | Carpet | South | Condition: New | Good | Fair | Poor |
| | | East | Condition: New | Good | Fair | Poor |
| | | West | Condition: New | Good | Fair | Poor |

Comments: _____

| | | | | | |
|-----------|----------------|-----|----|-----|--------------|
| Utilities | GAS | Yes | No | | |
| | SMOKE DETECTOR | Yes | No | Age | UNKNOWN |
| | HEAT DETECTOR | Yes | No | Age | NOT REQUIRED |