

# SITE INSPECTION FORM

Date: 6/7/2022  
Address: 80 State Highway Route 6

Building Name/Number: CABIN #7

## Building Features

Building Construction Type			Wood Frame	Cmu Block	Wood Frame/Cmu Block			Metal Mobile Home	
Location:									
Roof		Type	ASPHALT	Front	Condition: New	Good	Fair	Poor	
				Rear	Condition: New	Good	Fair	Poor	

Comments: \_\_\_\_\_  
\_\_\_\_\_

Exterior Walls		Type	WOOD	Location:	North	Condition: New	Good	CAA	Poor
					South	Condition: New	Good	Fair	Poor
					East	Condition: New	Good	Fair	Poor
					West	Condition: New	Good	Fair	Poor

Comments: All exterior walls above grade  
\_\_\_\_\_

Windows/Doors		Type	UNKNOWN	Location:	North	Condition: New	Good	Fair	Poor
					South	Condition: New	Good	Fair	Poor
					East	Condition: New	Good	Fair	Poor
					West	Condition: New	Good	Fair	Poor

Comments: \_\_\_\_\_  
\_\_\_\_\_

Foundation		Type	Slab	Crawlspace	Yes	No			
			Frost Wall						
			On Cmu Blocks/Piers	North	Condition:	New	Good	Fair	Poor
			Full Foundation	South	Condition:	New	Good	Fair	Poor
				East	Condition:	New	Good	Fair	Poor
				West	Condition:	New	Good	Fair	Poor

Comments: \_\_\_\_\_  
\_\_\_\_\_

Interior:		Ceiling Type	CEILING TILE	North	Condition: New	Good	Fair	Poor
				South	Condition: New	Good	Fair	Poor
				East	Condition: New	Good	Fair	Poor
				West	Condition: New	Good	Fair	Poor

Comments: Homasote Ceiling Tiles  
\_\_\_\_\_

Wall Type	WALL BOARD	North	Condition: New	Good	Fair	Poor
	WOOD WAINSCOT	South	Condition: New	Good	Fair	Poor
		East	Condition: New	Good	Fair	Poor
		West	Condition: New	Good	Fair	Poor

Comments: Homasote Wall Board  
\_\_\_\_\_

Floor Type	Vinyl	North	Condition: New	Good	Fair	Poor
	Carpet	South	Condition: New	Good	Fair	Poor
		East	Condition: New	Good	Fair	Poor
		West	Condition: New	Good	Fair	Poor

Comments: \_\_\_\_\_

Utilities	GAS	Yes	No		
	SMOKE DETECTOR	Yes	No	Age	UNKNOWN
	HEAT DETECTOR	Yes	No	Age	NOT REQUIRED