

SITE INSPECTION FORM

Date: 6/7/2022
Address: 80 State Highway Route 6

Building Name/Number: CABIN # 5/ #6 Duplex

Building Features

Building Construction Type		Wood Frame	Cmu Block	Wood Frame/Cmu Block	Metal Mobile Home
Location:					
Roof		Type	ASPHALT	Front	Condition: New Good Fair Poor
				Rear	Condition: New Good Fair Poor

Comments: _____

Location:					
Exterior Walls		Type	WOOD	North	Condition: New Good CAA Poor
				South	Condition: New Good Fair Poor
				East	Condition: New Good Fair Poor
				West	Condition: New Good Fair Poor

Comments: Portions on exterior wall at or below grade

Location:					
Windows/Doors		Type	UNKNOWN	North	Condition: New Good Fair Poor
				South	Condition: New Good Fair Poor
				East	Condition: New Good Fair Poor
				West	Condition: New Good Fair Poor

Comments: _____

Foundation		Type	Slab	Crawlspace	Yes	No
			Frost Wall			
			On Cmu Blocks/Piers	North	Condition: New	Good Fair Poor
			Full Foundation	South	Condition: New	Good Fair Poor
				East	Condition: New	Good Fair Poor
				West	Condition: New	Good Fair Poor

Comments: _____

Interior:		Ceiling Type	CEILING TILE	North	Condition: New Good Fair Poor
				South	Condition: New Good Fair Poor
				East	Condition: New Good Fair Poor
				West	Condition: New Good Fair Poor

Comments: Homasote Ceiling Tiles

Wall Type	WALL BOARD	North	Condition: New Good Fair Poor
	WOOD WAINSCOT	South	Condition: New Good Fair Poor
		East	Condition: New Good Fair Poor
		West	Condition: New Good Fair Poor

Comments: Homasote Wall Board

Floor Type	Vinyl	North	Condition: New Good Fair Poor
	Carpet	South	Condition: New Good Fair Poor
		East	Condition: New Good Fair Poor
		West	Condition: New Good Fair Poor

Comments: _____

Utilities	GAS	Yes	No
	SMOKE DETECTOR	Yes	No Age UNKNOWN
	HEAT DETECTOR	Yes	No Age NOT REQUIRED