

SITE INSPECTION FORM

Date: 6/7/2022
Address: 80 State Highway Route 6

Building Name/Number: CABIN #1

Building Features

Building Construction Type			Wood Frame	Cmu Block	Wood Frame/Cmu Block			Metal Mobile Home	
Location:									
Roof		Type	ASPHALT	Front	Condition:	New	Good	Fair	Poor
				Rear	Condition:	New	Good	Fair	Poor

Comments: _____

Exterior Walls		Type	WOOD	Location:	North	Condition: New	Good	Fair	Poor
					South	Condition: New	Good	Fair	Poor
					East	Condition: New	Good	Fair	Poor
					West	Condition: New	Good	Fair	Poor

Comments: Portions on exterior wall at or below grade

Windows/Doors		Type	UNKNOWN	Location:	North	Condition: New	Good	Fair	Poor
					South	Condition: New	Good	Fair	Poor
					East	Condition: New	Good	Fair	Poor
					West	Condition: New	Good	Fair	Poor

Comments: _____

Foundation		Type	Slab	Crawlspace	Yes	No			
			Frost Wall						
			On Cmu Blocks/Piers	North	Condition:	New	Good	Fair	Poor
			Full Foundation	South	Condition:	New	Good	Fair	Poor
				East	Condition:	New	Good	Fair	Poor
				West	Condition:	New	Good	Fair	Poor

Comments: _____

Interior:		Ceiling Type	CEILING TILE	North	Condition: New	Good	Fair	Poor
				South	Condition: New	Good	Fair	Poor
				East	Condition: New	Good	Fair	Poor
				West	Condition: New	Good	Fair	Poor

Comments: Homasote Ceiling Tiles

Wall Type	WALL BOARD	North	Condition: New	Good	Fair	Poor
	WOOD WAINSCOT	South	Condition: New	Good	Fair	Poor
		East	Condition: New	Good	Fair	Poor
		West	Condition: New	Good	Fair	Poor

Comments: Homasote Wall Board

Floor Type	Vinyl	North	Condition: New	Good	Fair	Poor
	Carpet	South	Condition: New	Good	Fair	Poor
		East	Condition: New	Good	Fair	Poor
		West	Condition: New	Good	Fair	Poor

Comments: _____

Utilities	GAS	Yes	No		
	SMOKE DETECTOR	Yes	No	Age	UNKNOWN
	HEAT DETECTOR	Yes	No	Age	NOT REQUIRED